

SPH





Рис. 1

Рис. 2

Обозначение	Размеры					Пластина	 Ключ	Исполнение
	H=h	W	L	S	T-Max			
SPH316R/L	16	16	100	16,3	16	BP300 BP300 BP400	SW80	Рис. 1
SPH320R/L	20	20	120	20,3	20			
SPH420R/L	20	20	120	20,4	25			
SPH520R/L	20	20	120	20,5	30	BP500 BP300 BP400 BP500		
SPH325R/L	25	25	150	25,3	25			
SPH425R/L	25	25	150	25,4	30			
SPH525R/L	25	25	150	25,5	35			
SPH316R/LS	16	16	100	16,3	16,5	BP300 BP300 BP400 BP500		
SPH320R/LS	20	20	120	20,3	20			
SPH420R/LS	20	20	120	20,4	25			
SPH520R/LS	20	20	120	20,5	30	BP300 BP400 BP500		
SPH325R/LS	25	25	150	25,3	25			
SPH425R/LS	25	25	150	25,4	30			
SPH525R/LS	25	25	150	25,5	35			

